


C-2 Combination Meter Circuit Diagram (Indicator)


S6RW0C910E020



C-3 Combination Meter Circuit Diagram (Warning Light)

S6RW0C910E021

- (A) Except Taiwan
- (B) Taiwan
- (C) Without seat heater
- (D) With seat heater



I6RW0D910915-01